INSPECTION REPORT

Partial Complete XXX Exploration Inspection Date: 06/10/2003/ Time: 09:30-03:00 Date of Last Inspection: 05/15/2003

Mine Name: <u>Hiawatha Complex</u>	County: <u>Carbon</u>	Permit Number: <u>C/007/011</u>
Permittee and/or Operator's Name: Hiawath	na Coal Company	
Business Address: P.O. Box 1245, Hunting	ton, Utah 84528	
Company Official(s): Alden Gustafson		
State Official(s): <u>Joe Helfrich</u>	_Federal Official(s):	None
Weather Conditions: <u>Clear, Temp 65°F</u>		
Type of Mining Activity: Underground XX	X Surface Prep	PlantOther
Existing Acreage: Permitted 12,177 Distur	rbed 290 Regraded	Seeded
Status: Active Reclamation	_	

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For <u>complete inspections</u> provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
 - b. For <u>partial inspections</u> check only the elements evaluated.
- 2. Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

		EVALUATED	N/A	COMMENTS	NOV/ENF
1.	PERMITS, CHANGE, TRANSFER, RENEWAL, SALE	[X]		[X]	
2.	SIGNS AND MARKERS	[X]	ΞĪ	<u>[X]</u>	
3.	TOPSOIL	[X]	Ĺĺ	Ĺĺ	Ĺĺ
4.	HYDROLOGIC BALANCE:				
a.	DIVERSIONS	[X]			
b.	SEDIMENT PONDS AND IMPOUNDMENTS	[X]		[X]	
c.	OTHER SEDIMENT CONTROL MEASURES	[X]			
d.	WATER MONITORING	[X]		[X]	
e.	EFFLUENT LIMITATIONS	[X]	\Box		
5.	EXPLOSIVES	[X]			
6.	DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES	[X]			
7.	COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS	[X]		[X]	
8.	NONCOAL WASTE	[X]			
9.	PROTECTION OF FISH, WILDLIFE AND RELATED				
	ENVIRONMENTAL ISSUES	[X]			
10.	SLIDES AND OTHER DAMAGE	[X]			
11.	CONTEMPORANEOUS RECLAMATION	[X]			
12.	BACKFILLING AND GRADING	[X]			
13.	REVEGETATION	[X]			
14.	SUBSIDENCE CONTROL	[X]			
15.	CESSATION OF OPERATIONS	[X]			
16.	ROADS:				
a.	CONSTRUCTION/MAINTENANCE/SURFACING	[X]			
b.	DRAINAGE CONTROLS	[X]			
17.	OTHER TRANSPORTATION FACILITIES	[X]			
18.	SUPPORT FACILITIES/UTILITY INSTALLATIONS	[X]			
19.	AVS CHECK (4 th Quarter- April, May, June)	[X]		[X]	
20.	AIR QUALITY PERMIT	[X]		[X]	
21.	BONDING & INSURANCE	[X]		[X]	

INSPECTION REPORT

(Continuation Sheet)

PERMIT NUMBER: <u>C/007/011</u> DATE OF INSPECTION: <u>06/10/2003</u>

(COMMENTS ARE NUMBERED TO CORRESPOND WITH TOPICS LISTED ABOVE)

1. PERMITS, CHANGE, TRANSFER, RENEWAL, SALE

The DOGM permit was issued on March 14, 2002 and expires on March 14, 2007. The permit renewal included two conditions. These conditions were: electronic submittals of water monitoring and complying with the results of any Order resulting from the Informal Hearing (requested by Huntington Cleveland Irrigation Company) held on April 11, 2002. Receipt of clean copies of amendment #AM02B-3 will satisfy the requirements of the order.

Other documents include the following:

- -Certificate of Insurance by Scottsdale Insurance Co. Policy # CLS0668789 effective 01/27/2003 and expires 01/27/2004.
- -UPDES Permit UT-0023094 issued 10/01/1999 and expires 09/30/2004 at midnight.
- -Air Quality Permit BAQE-502-89 issued 07/25/1989 and remains in effect.
- -Bond is an irrevocable letter of credit issued by Bank One in the amount of \$2,838,000.

There is one amendment pending, AM02B. This amendment pertains to the revision of chapters 5, 6, and 7 of the MRP. Gregg Galecki, lead reviewer, finalized the amendment for approval on June 6, 2003. Clean copies are due on July 3, 2003.

2. SIGNS AND MARKERS

Mine ID signs were present at all public entrances and contained the appropriate information. The ID signs for MSHA Slurry Impoundments #1 & #5 were in place. The ID sign for the refuse pile was in place. All other markers observed during the inspection met the coal rules.

4B. HYDROLOGIC BALANCE: SEDIMENT PONDS AND IMPOUNDMENTS

The sediment ponds were inspected on June 3, 2003, indicating no signs of hazards or structural weaknesses. Slurry ponds 1 and 5 were inspected on June 2, 2003, with no indications of structural weakness or hazards.

4D. HYDROLOGIC BALANCE: WATER MONITORING

Lab sheets for First and second quarter 2003 water monitoring data were available for review. Water monitoring sites were sampled April 8, 2003. DMR's were current through April 2003. UTM coordinates and photos were taken for sites ST-2 and SP-11.

7. COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS

The refuse pile appeared stable and was inspected on June 2, 2003. No visible hazards were observed during the inspection. Removal of fines from the slurry pond, located adjacent to the refuse pile, is scheduled to resume in the near future.

INSPECTION REPORT

(Continuation Sheet)

PERMIT NUMBER: <u>C/007/011</u>	DATE OF INSPECTION: <u>06/10/2003</u>
---------------------------------	---------------------------------------

19. AVS CHECK

Ownership and control information for the year 2003 will be submitted and reviewed with the annual report.

20. AIR QUALITY PERMIT

Air Quality Permit BAQE-502-89 was issued on 07/25/1989 and still remains in effect.

21. BONDING AND INSURANCE

The reclamation bond was reviewed. The bond is an irrevocable letter of credit issued by Bank One.

The Liability Insurance is adequate and meets all of the minimum requirements. Explosion coverage is provided. The insurance is through Scottsdale Insurance Co. Policy # CLS0668789 effective 01/27/2003 and expires 01/27/2004.

Inspector's Signature:			Date:	June 12, 2003
	Joseph C. Helfrich	#1	="	

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas & Mining.

cc: James Fulton, OSM
Elliot Finley, Hiawatha, via email
Price Field office
O:\007011.HIA\Compliance\2003\c_0610.doc